

№ на пот. точка	Съединение на външните връзки между апаратите в таблото	Забележка
1	2	3
61	x2:46;3K2:11;	
62	3K2:12;3K1:A1;	
63	x2:54;3K1:11;	
64	3K1:12;3K2:A1;	
65	x2:52;3K3:A1;	
66	x2:61;K5:11;	
67	K5:14;4K2:11;	
68	4K2:12;4K1:A1;	
69	x2:64;K5:21;	
70	K5:24;4K1:11;	
71	4K1:12;4K2:A1;	
72	x2:67;K6:11;	
73	K6:14;5K2:11;	
74	5K2:12;5K1:A1;	
75	x2:70;K6:21;	
76	K6:24;5K1:11;	
77	5K1:12;5K2:A1;	
78	x2:71;4K1:13;4K2:13;	
79	4K1:14;4K3:A1;4K2:14;4K3:17;4K4:17;4K5:17;	
80	4K3:18;4K4:A1;	
81	4K4:18;4K5:A1;	
82	4K5:18;4K6:A1;	
83	F14:2;x2:72;K5:33;K6:33;	
84	x2:73;K5:A1;	
85	x2:74;K6:A1;	
86	K5:34;x2:55;	
87	K6:34;x2:57;	

					“МИНПРОЕКТ” ЕАД	Черт. No: 355–2017	Лист: 2
				04.17			
Изм.	Бр	Док	№	Погн			